






Assembling instruction




x2




x2




x4



x6




x2



M8x30

x4




M8x16

x4




M8x60


x10



x2




x2




M6x16

x8




x4



#13

x1




#5

x1





#4


x1





x44


















x4

