









Assembling instruction



D



cx4



D50/D70


d x 1





M8x20


c x 12




D	a x 4	b x 4	c x 4				
							




A




B





C




D







A



B



C



D

