






Assembling instruction



x7



x4




M8

x4




M8

x4




M80x30

x3




D50

x7



x7



x1



x1

