




Motstands justering




COMFY SPISESTOL


Base 10000




Base 10000



1



2



Montering av armer

